

TIREMAAX® CP TIRE INFLATION SYSTEM

This TIREMAAX® CP controller assembly has been factory preset to:

80 psi

If the lamp remains on continuously for more than 10 minutes, one or more tires may be low or the system requires service.

Install the enclosure so drain hole is located on the bottom.

For complete service details, refer to Hendrickson publication L995, TIREMAAX CP Installation, Service and Troubleshooting Procedures, or call the Hendrickson technical service department at 800-455-0043 in the United States or 800-668-5360 in Canada.

Trailer Suspension Systems
2070 Industrial Pkcs SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045
Fax 800.696.4416



Trailer Suspension Systems
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
905.789.1030
Fax 905.789.1033