H: TECHNICAL PROCEDURE **PRECISION240® SPINDLE NUT SYSTEM**

SUBJECT: Hubcap Compatibility and Kit Information

LIT NO: T77002 DATE: July 2016

REVISION: B

ABOUT PRECISION240® NUT SYSTEM


This kit contains a patented PRECISION240® nut system: spindle nut (Figure 1), interlock washer and two washer retaining screws.

Hubcap compatibility is listed in the table on the following pages. For questions, contact Hendrickson Trailer Technical Services at 866-RIDEAIR (743-3247) or email HTTS@Hendrickson-intl.com.

RELATED LITERATURE

The table below includes a list of literature relative to PRECISION240 spindle nut applications.

NAME	DESCRIPTION
L583	Comprehensive Warranty Statement
<u>T71005</u>	PRECISION320 [®] , PRECISION240 [®] Install Poster
T72006	HXL3® Wheel-end Maintenance Procedures
<u>T72007</u>	HXL5® Wheel-end Maintenance Procedures



0.94" (23.88 mm) thick

Figure 1: PRECISION240® HN spindle nut system



This spindle nut is larger than some others offered by Hendrickson. If improper components are used, this could lead to interference between the hubcap and powdered metal nut system. It is therefore recommended to **use only genuine Hendrickson or Hendrickson approved replacement components**. Refer to the table below for a list of hubcaps that are compatible with the PRECISION240 powdered metal nut.

SPINDLE TYPE	HUB CAP Brand	PICTURE	[H] P/N	MANUFACTURER P/N	TIRE INFLATION SYSTEM (TIS)	PRECISION240 [®] NUT Compatibility?	
	Hendrickson		A-28508	HS009P	None	No	
			C-32049-1	N/A	TIREMAAX® PRO1	Yes	
			C-32055-1	N/A	TIREMAAX PRO1	Yes	
HN ²			C-32055-3	N/A	TIREMAAX PRO1	Yes	
			C-32068-1	N/A	TIREMAAX CP Integrated 1	Yes	
			C-32068-3	N/A	TIREMAAX CP Integrated ¹	Yes	
		HXL5	C-33376	N/A	None	Yes	
 For TIREMAAX[®] PRO and CP Integrated, allowance must be made for hubcap mounted rotary union. Refer to <u>T57001 Wheel-end Considerations</u>. The PRECISION240[®] nut system is designed for HN tapered spindles only. 							

³ Refer to <u>L583</u> warranty coverage information when installing non-Hendrickson TIS on Hendrickson suspensions.

HUBCAP COMPATIBILITY AND KIT INFORMATION

SPINDLE TYPE	HUB CAP Brand	PICTURE	[H] P/N	MANUFACTURER P/N	TIRE INFLATION SYSTEM (TIS)	PRECISION240 [®] NUT Compatibility?
HN 2	Hendrickson		C-34784	N/A	None	Yes
		E.	E32628-1	N/A	None	Yes
	Stemco		A-1974	343-4009	None	Yes
		3	A-23986	348-5307	None	Yes
		6	A-23987	349-4009	None	Yes
			C-31292	343-4307	TIREMAAX® EC & CP ³	Yes

² The PRECISION240[®] nut system is designed for HN tapered spindles only.

 $_{\scriptscriptstyle 3}$ Refer to <u>L583</u> warranty coverage information when installing non-Hendrickson TIS on Hendrickson suspensions.

HUBCAP COMPATIBILITY AND KIT INFORMATION

SPINDLE TYPE	HUB CAP Brand	PICTURE	[H] P/N	MANUFACTURER P/N	TIRE INFLATION SYSTEM (TIS)	PRECISION240 [®] NUT COMPATIBILITY?	
	Dual Dynamics		N/A	201-GN	None	Yes	
		O	C-26492	N/A	TIREMAAX® EC & CP ³	Yes	
			C-26491	N/A	TIREMAAX EC & CP ^{_3}	Yes	
HN ²			C-28572	207-PSN	None	Yes	
			C-29467	202-G	None	Yes	
			C-25885	106819	None	Yes	
			C-25886	10018622	None	Yes	
 For TIREMAAX[®] PRO and CP Integrated, allowance must be made for hubcap mounted rotary union. Refer to <u>T57001 Wheel-end Considerations</u>. The PRECISION240[®] nut system is designed for HN tapered spindles only. Refer to <u>L583</u> warranty coverage information when installing non-Hendrickson TIS on Hendrickson suspensions. 							

HUBCAP COMPATIBILITY AND KIT INFORMATION

SPINDLE TYPE	HUB CAP Brand	PICTURE	[H] P/N	MANUFACTURER P/N	TIRE INFLATION SYSTEM (TIS)	PRECISION240 [®] NUT Compatibility?
	Federal Mogul		N/A	343-009	None	No
			N/A	340-350	PSI≟	Yes
			N/A	HWB-009-4S	None	Yes
			N/A	HWG-609 None		Yes
HN ²			N/A	HWJ-609	None	Yes
			N/A	HWK-609	None	Yes
		6.	N/A	HWM-650	PSI≟	Yes
		B.	N/A	HWN-350	PSI≟	Yes
		P Integrated, allowance mus	N/A	HWQ-009-4	None	Yes

² The PRECISION240[®] nut system is designed for HN tapered spindles only.

³ Refer to <u>L583</u> warranty coverage information when installing non-Hendrickson TIS on Hendrickson suspensions.

NOTES:			

Call Hendrickson at 866.RIDEAIR (743.3247) for additional information.



 TRAILER COMMERCIAL VEHICLE SYSTEMS

 2070 Industrial Place SE

 Canton, OH 44707-2641 USA

 866.RIDEAIR (743.3247)

 330.489.0045 • Fax 800.696.4416

Hendrickson Canada

250 Chrysler Drive, Unit #3 Brampton, ON Canada L6S 6B6 800.668.5360 905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana

Circuito El Marqués Sur #29 Parque Industrial El Marqués Pob. El Colorado, Municipio El Marqués, Querétaro, México C.P. 76246 +52 (442) 296.3600 • Fax +52 (442) 296.3601

www.hendrickson-intl.com