
HPARTS LIST


COMFORT AIR® Rear Air Suspension for Thomas Built Buses

LIT NO: SP-295

DATE: September 2015 **REVISION**: A







2 SP-295



		VEHIC	CLE	I			VEHICLE
ĶEY N	O. PART NO.	DESCRIPTION	QTY.		D. PART NO.	DESCRIPTION	QTY.
1	60784-000		2	21	56805-000	Top Pad	2
	60632-038	QUIK-ALIGN Pivot Bushing Service Kit,			48718-007	U-bolt Service Kit, Axle Set	
		Axle Set , Includes Key Nos. 2-6, 13, 15, 47				Includes Key Nos. 22-25	
	34013-103	QUIK-ALIGN Pivot Bushing Service Kit,		22	47417-008	%"-14 UNF x 15½" U-bolt	4
		One Side, Includes Key Nos. 4-6, 13, 15, 47		23	22962-002	%" Hardened Flat Washer	8
	60632-013	QUIK-ALIGN® Collar Service Kit, Axle Set,		24	50765-000	%" 14 UNF U-bolt Locknut	8
		Includes Key Nos. 2-6		25	48574-000	Spherical Washer	8
2	64633-000	QUIK-ALIGN Concentric Collar	3	26	48531-015	Spring Seat Spacer	2
3	64632-000	QUIK-ALIGN Eccentric Collar	1	27	56501-020	Spring Seat, 4.5° Pinion Angle LH/RH - 5"	2
4	68217-000	1"-8 UNC x 7½" Bolt	2	28	50216-000	Axle Bottom Cap	2
5	68232-000	1" Hardened Washer	4	29	66279-001	Cross Channel	1
6	68218-000	1"-8 UNC Locknut	2		57356-000	Lower Shock Bracket Assembly,	2
	60925-002	Air Spring Assembly, Includes Key Nos. 7-8	2			Includes Key Nos. 30-33	
		and Fasteners		30		*Lower Shock Bracket	2
7		*Air Spring	2	31	50764-002	34"-10 UNC x 51/2" Bolt	2
8	57096-002	Air Spring Bracket	2	32	22962-001	34" Hardened Washer	4
-	49177-006	Lower Air Spring Fastener Service Kit, Axle Se	t,	33	49842-000	34"-10 UNC Locknut	2
		Includes Key Nos. 9-10		34		**3/4"-10 UNC x 31/2" Bolt	2
9	22962-014	1/2" Flat Washer	2	35		**3/4"-10 UNC x 3" Bolt	2
10	17700-010	1/2"-13 UNC Nylocknut	2	36		**3/4" Hardened Washer	8
	60779-000	Main Support Assembly,	2	37		**3/4"-10 UNC Locknut	4
		Includes Key Nos. 11-20		38	60670-006	Shock Absorber	2
11		*Main Support Member	2		57322-002	Upper Shock Bracket Assembly,	2
12		*Secondary Leaf	2			Includes Key Nos. 39-42	
13	58648-000	Pivot Bushing	2	39		*Upper Shock Bracket	2
14	37674-051	Liner	4	40	50368-000	1/2"-13 UNC Serrated Shank Bolt	2 2
15	64817-000	Plastic Isolator Puck	4	41	22962-031	½" Hardened Washer	2
16	60392-000	Spring Eye Clip	2	42	49846-000	½"-13 UNC Locknut	2
	49175-026	Spring Clip Fastener Service Kit, Axle Set,		43	62000-570	Transverse Torque Rod Assembly	1
		Includes Key Nos. 17-19		44	47691-000	Torque Rod Bushing	2
17	64272-004	Spring Clip Sleeve	4	45	49689-000	Torque Rod Shim	As Req.
18	37042-006	%-14 UNC Bolt	2	46	22186-000	Transverse Torque Rod Frame Bracket	i
19	37587-000	%6"-14 UNC Nut	2	47	70867-001	P-80 Lubricant - 10 ml (Not Shown)	As Req.
20		*Clip Bolt Spacer	2			,	
		·					

NOTE

SP-295 3

 $[\]ensuremath{^{*}}$ Item included in assembly only, part not sold separately.

^{**} Not supplied by Hendrickson, used for reference only. Refer to vehicle manufacturer for more information. Hendrickson is not responsible for components supplied by vehicle manufacturer.



■ Special Tools

QUIK-ALIGN PIVOT BUSHING TOOL



Hendrickson Part No. 66086-203L

Reference Literature No. 59310-061

QUIK-ALIGN SOCKET TOOL



Hendrickson Part No. 66086-200

OTC Part No. 1767

Visit otctools.com

TORQUE ROD BUSHING FUNNEL TOOL



Hendrickson Part No. 66086-001

ULTRA ROD Assembly Funnel Tool

This is a general parts list to provide directional information. Components may vary by model. Questions in regards to parts, contact Hendrickson Truck Parts at 1.866.755.5968 (Toll-free U.S. and Canada), 630.910.2800 (Outside U.S. and Canada) or e-mail: truckparts@hendrickson-intl.com.

Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration. Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.

Call Hendrickson at 1.866.755.5968 (toll-free) or 1.630.910.2800 for additional information.



www.hendrickson-intl.com

TRUCK COMMERCIAL VEHICLE SYSTEMS

800 South Frontage Road Woodridge, IL 60517-4904 USA 1.866.755.5968 (Toll-free U.S. and Canada) 1.630.910.2800 (Outside U.S. and Canada) Fay 1 630 910 2899