

# WARNING

**DO NOT REMOVE LIFTING STRAP HARDWARE FROM FLANGE PLATE WHEN COIL SPRING IS UNDER TENSION. Doing so could cause unexpected, sudden and violent movement of suspension parts that can result in serious injury or property damage. Refer to Hendrickson publication L765, VANTRAAX® HRRNT 40K / HRRT 50K Maintenance Procedures, for complete coil spring tension releasing instructions.**

Trailer Suspension Systems  
2070 Industrial Place SE  
Canton, OH 44707-2600 USA  
800.455.0043  
330.489.0045  
Fax 800.696.4416



Trailer Suspension Systems  
250 Chrysler Drive, Unit #3  
Brampton, ON L6S 6B6 Canada  
905.789.1030  
Fax 905.789.1033

L813 Rev B 12-03 Printed in USA.

[www.hendrickson-intl.com](http://www.hendrickson-intl.com)

All Rights Reserved.  
The Boler Company. Copyright ©2003.

## NOTES

1. Shown actual size.
2. Use one of the following adhesives:
  - a. Fasson Tire Label II (TL2). Hot melt rubber on latex impregnated paper with barrier coating on adhesive side.
  - b. P1480.
3. Finished decal height to be **no more** than 3.1875 inches.